

1/10




Fig. 1A

2/10




Fig. 3

Reference number "358" changed to "36"

Reference number "75" changed to "74"

Reference number "75" changed to "75"




Fig. 1B




Fig. 2

**ANNOTATED DRAWING SHEET SHOWING CHANGES
Entitled: DUAL-DIRECTION PULLEY SYSTEM
Application No.: 10/635,072; Filed: August 6, 2003;
Atty. Docket No.: 1909/US/2; USPTO Customer No.: 20686**

3/10




Fig. 4




Fig. 5

ANNOTATED DRAWING SHEET SHOWING CHANGES
Entitled: DUAL-DIRECTION PULLEY SYSTEM
Application No.: 10/635,072; Filed: August 6, 2003;
Atty. Docket No.: 1909/US/2; USPTO Customer No.: 20686

5/10






Fig. 6



**ANNOTATED DRAWING SHEET SHOWING CHANGES
Entitled: DUAL-DIRECTION PULLEY SYSTEM
Application No.: 10/635,072; Filed: August 6, 2003;
Atty. Docket No.: 1909/US/2; USPTO Customer No.: 20686**

7/10



8/10




Fig. 9

9/10




Fig. 10

10/10




Fig. 11